

THE INFORMATION CONTAINED HEREIN IS THE EXCLUSIVE PROPERTY OF VIRGINIA PANEL CORPORATION AND IS SUBMITTED FOR USE BY THE CUSTOMER ONLY. THE DATA SHALL NOT BE DUPLICATED, USED, OR DISCLOSED IN WHOLE OR IN PART FOR ANY PURPOSE OTHER THAN TO MAINTAIN THE EQUIPMENT PROVIDED. CONSULT WITH VIRGINIA PANEL CORPORATION ENGINEERING IF MORE DETAIL IS REQUIRED.

REMOVE CARRY HANDLE AND FOUR RUBBER FEET FROM PXI CHASSIS. HANDLE WILL BE MOUNTED TO METAL PLATE PROVIDED WITH THE PMA-1115. SLIDE THE VPC ADAPTER (310113504) OVER THE PXI CHASSIS. THE POWER BUTTON OF THE PXI CHASSIS SHOULD BE ORIENTED TOWARDS THE TOP OF THE VPC ADAPTER. REPLACE THE RUBBER FEET WHICH NOW WILL ALSO GO THROUGH THE VPC ADAPTER. SECURE THE TOP OF THE VPC PART AND THE METAL PLATE PROVIDED WITH THE PMA-1115 (NOW WITH HANDLE ON IT) WITH PROVIDED M4 SCREWS. INSTALL THE PMA-1115 PER NATIONAL INSTRUMENTS INSTRUCTIONS. INSTALL THE REMAINING SCREWS ON THE TOP SIDE.

DIMENSIONS ARE SHOWN AS: <div> <div>[MILLIMETERS]</div> <div>INCHES</div> </div>	SIZE	CAGE CODE	DWG.NO.		REV
	C	18117	310113504		A
	SCALE: 1:4	310113504	9/9/08	SHEET	1 OF 1

NI PXI-1042 TO G10 ADAPTER

DIMENSIONS ARE SHOWN AS: <div> <div>[MILLIMETERS]</div> <div>INCHES</div> </div>	SIZE	CAGE CODE	DWG.NO.		REV
	C	18117	310113504		A
	SCALE: 1:4	310113504	9/9/08	SHEET	1 OF 1