

Tech Tips: Slide Measuring Dimensions

1. Measure dimension A to determine the proper slide kit.

NOTE: Make sure the slide length does not exceed dimensions A plus B.

2. Dimension C is for Rack Extender Kit use. See Rack Extender Kit Dimensions Tech Tip.

